

AMENDMENTS TO THE DRAWINGS

“Replacement Sheets” are attached which include a clean version of amended Figures 1, 4, 8, 9a-9c and 15. The attached sheets replace the original sheets including Figures 1, 4, 8, 9a-9c and 15.

“Annotated Sheets Showing Changes” are also attached which include a marked-up version of Figures 1, 4, 8, 9a-9c and 15.

Figures 1, 4, 8, 9a-9c and 15 were amended it include labels on the boxes.

REMARKS

Applicants, by this supplemental amendment, hereby supplements their response to the Office Action mailed October 17, 2007 in the above-identified U.S. patent application. The present amendment is supplemental in nature, as Applicants' amendment filed February 19, 2008 was fully responsive to all of the rejections raised in the outstanding Office Action.

The Office Action objected to the drawing because blocks 3-14 of Fig. 1,
blocks 21, 22 and 24 of Fig. 4,
blocks 17, 26-29 of Fig. 8,
blocks 30-32, 34-37 and 40-43 of Figs 9a-9c, and
blocks 41-56 of Fig. 15 were not in compliance with 37 CFR 1.121(d).

Applicants submit herewith annotated sheets showing the changes to blocks 3-14 of Fig. 1, blocks 21, 22 and 24 of Fig. 4, blocks 17, 26-29 of Fig. 8, blocks 30-32, 34-37 and 40-43 of Figs 9a-9c and blocks 41-52 of Fig. 15. Replacement sheets incorporating these changes are also attached. Applicants have not added labels to elements identified by reference numerals 53-56 53, 54, 55 because these elements are configuration signals, not blocks as identified in the Office Action.

CONCLUSION

A Notice of Allowance is respectfully requested. The Examiner is requested to call the undersigned at the telephone number listed below if this communication does not place the case in condition for allowance.

If this response is not considered timely filed and if a request for an extension of time is otherwise absent, Applicant hereby requests any necessary extension of time. If there is a fee occasioned by this response, including an extension fee, that is not covered by an enclosed check, please charge any deficiency to Deposit Account No. 23/2825.

Dated: March 11, 2008

Respectfully submitted,

By: 
James H. Morris
Registration No.: 34,681
WOLF, GREENFIELD & SACKS, P.C.
Federal Reserve Plaza
600 Atlantic Avenue
Boston, Massachusetts 02210-2206
617.646.8000

1/24




Fig. 1

Delay unit
conjugator for

Fig. 4

23

Multiplexer

OFDM
signal

To 20
and 17

Interpolator

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

81

82

83

84

85

86

87

88

89

90

91

92

93

94

95

96

97

98

99

100

101

102

103

104

105

106

107

108

109

110

111

112

113

114

115

116

117

118

119

120

121

122

123

124

125

126

127

128

129

130

131

132

133

134

135

136

137

138

139

140

141

142

143

144

145

146

147

148

149

150

151

152

153

154

155

156

157

158

159

160

161

162

163

164

165

166

167

168

169

170

171

172

173

174

175

176

177

178

179

180

181

182

183

184

185

186

187

188

189

190

191

192

193

194

195

196

197

198

199

200

201

202

203

204

205

206

207

208

209

210

211

212

213

214

215

216

217

218

219

220

221

222

223

224

225

226

227

228

229

230

231

232

233

234

235

236

237

238

239

240

241

242

243

244

245

246

247

248

249

250

251

252

253

254

255

256

257

258

259

260

261

262

263

264

265

266

267

268

269

270

271

272

273

274

275

276

277

278

279

280

281

282

283




Fig. 9a




Fig. 9b

12/24




Fig. 9c




Fig. 8




Fig. 15